



Helicopter Technology Company

12902 South Broadway, Los Angeles, CA 90061 VOICE: 310-523-2750 / FAX: 310-523-2745 / www.helicoptertech.com

Issue Date: April 20, 2016

To whom it may concern,

This letter serves to appoint the following company as a Helicopter Technology Company (HTC) Factory Authorized Repair Facility for the listed HTC Part Numbers (P/N's). This document in no way supercedes any prevailing regulations put forth by the Federal Aviation Administration (FAA).

Repair Station: Airborne Services BV
Kooiweg #40
Hoogerheide 4631 SZ
Netherlands
+31850657500

HTC P/N's: **500P2100-101, -103, and -105 Blade Assembly, Main Rotor**
(applicable on 369D and 369E)
500P2100-301, -303, and -305 Blade Assembly, Main Rotor
(applicable on 369A, 369H, 369HE, 369HM, and 369HS)
500P2300-501, -503, and -505 Blade Assembly, Main Rotor
(applicable on 369FF, 500N, and 600N)
500P3100-101, -103, and -105 Blade Assembly, Tail Rotor
(applicable on 369D and 369E, 2 Blade System)
500P3100-301, -303, and -305 Blade Assembly, Tail Rotor
(applicable on 369D and 369E, 4 Blade System)
500P3300-501, -503, and -505 Blade Assembly, Tail Rotor
(applicable on 369A, 369H, 369HE, 369HM, and 369HS)
500P3500-701, -703, and -705 Blade Assembly, Tail Rotor
(applicable on 369FF)

This appointment is valid until revoked by HTC.

Sincerely,

Gary Burdorf
President